

SNMP Firmware

Release Notes, Version 1.34

Version 1.34

[2186] SNMP values for discharge current and float current are displayed with correct polarity.

Version 1.32

[2061] Network connection is no longer lost after switching front switch from direct to network.

Version 1.30

[1800] Extra byte of data being received via the MODBUS request fixed.

[1709] Added functionality that will only send new alarms if the trap interval is set to 0.

[1708] Temperature values now have the correct value.